

# Fact Sheet


**multilift hp**  
**...more than just non-rotating**

## Safety...

What we produce and supply needs special care...  
...Care about consequences in case of failure.  
It's not just quality, it's safety that matters.

12.10.2008



## Why 'multilift hp 35' became our standard....



we decided to  
take the safest by making  
'multilift hp35' our standard.



Rather than walking the  
easy way by choosing  
the usual 17x7, 34x7  
or similar type  
rotation-resistant ropes,



For three simple, but most important reasons:

### 1. More functional reliability

because a four-strand core with filler strands offers a better rotation stability.

### 2. Longer service life

because configuration and composition of all components (wires and strands) result in a minimized number of wire cross points inside of the rope, ensuring a better wear resistance.

### 3. Better personal safety

because a two-layer construction allows a more reliable decision when to discard.